



CL Hard Surface II

APPLICATION **I**NSTRUCTIONS

STEP BY STEP

Step 1: Insert into bypasstray and print mirror imaged

Step 2: Print image in heavy to label 1 mode, mirror image

Step 3: Place substrate with image side face up

Step 4: Place imaged paper with image face down

Step 5: Place foam pad on top

Step 6: Press at 300F for 60 seconds

Step 7: Wait for substrate to cool and peel backing off cool.

APPLICATION

Paper Mode: ItemNo.: Print mode: Temperature: Time: Peel: Pressure: Heavy to Label 1 JPCLHS2S Mirror Image 300F 60 seconds Cool Heavy

All technical information and recommendations are based on tests we have conducted. Users should conduct their own tests before proceeding

Accessories Required

Computer, Color Laser Printer, Heat Press. Foam Heat Pad, Felt pad (optional).

Printable side The printable side (white glossy coated side) It is also the adhesive side.

Pressure Settings Heavy Pressure is required for the image to completely adhere to the hard substrate.

Image Design

This paper works best with a full bleed image. When designing your image, ensure that you bleed your image at least 0.5 inches more than the substrate. If you are not bleeding the image, it is recommended you trim the image to eliminate the background.

Notes

Peeling

Depending on the substrate you are imaging, the peel could be cool or hot. Please read instructions for substrate carefully. (see PDF instructions)

Care Instructions

After imaging, do not put in direct sunlight. Store at room temperature.

Storage

CL Hard Surface II has an indefinite shelf life when stored at room temperature. Keep away from direct heat, sunlight and humidity.

Recommended Fabrics

Wood Leather Card Board Crystal Glass White or Light Colored

Jacky Yan: +86-13147045331 +86-20-83375464 www.bestsub.com

Rm 4411, Grandview East International Plaza, No 372, Huanshi Dong Road, Yuexiu District, Guangzhou, 51000, China